

MT

BEST AVAILABLE COPY

SWANSON & BRATSCHUN, L.L.C.

1745 Shea Center Drive, Suite 330
Highlands Ranch, Colorado 80129
Telephone (303) 268-0066
Facsimile (303) 268-0065
e-Mail: firm@sbiplaw.com

FACSIMILE COVER PAGE

TO: Certificate of Correction Branch

FACSIMILE #: 703-308-6672

FROM: James L. Brown

DATE: November 15, 2006

Number of pages, including cover page 13 Faxed _____

Please call Elizabeth at (303) 268-0066 if you do not receive all pages or have trouble receiving this transmission.

THIS TRANSMISSION AND THE ACCOMPANYING DOCUMENTS MAY CONTAIN CONFIDENTIAL INFORMATION INTENDED ONLY FOR THE RECIPIENT NAMED ABOVE. IF YOU ARE NOT THE INTENDED RECIPIENT NAMED ABOVE, YOU ARE HEREBY NOTIFIED THAT ANY DISCLOSURE OR ACTION TAKEN BASED UPON THE CONTENT OF THIS TRANSMISSION IS PROHIBITED. IF YOU HAVE RECEIVED THIS INFORMATION IN ERROR, PLEASE NOTIFY OUR OFFICE IMMEDIATELY AND MAIL THIS TRANSMISSION TO OUR OFFICE.

Re: **U.S. Patent No. 6,957,534 B2**
Reach Adjustment Mechanism for a Master Cylinder
Lever of a Hydraulic Disc Brake
Our Ref.: AVID.18-2/C

Dear Sirs:

There were three Requests for Certificate of Correction mailed in the above-referenced patent. To date, only two Certificates of Correction have been correctly issued.

Attached is a copy of the date stamped card receipt for the 3rd Request for Certificate of Correction, received in the USPTO on November 21, 2005 and a copy of the submission. This Request has not been acted upon and this is the second request for action on this matter.

Please process this Request for Certificate of Correction and issue an appropriate Certificate as soon as possible. If you have any questions, please do not hesitate to call the undersigned or his assistant, Elizabeth Salacinski at 303-268-0066.

James L. Brown
Swanson & Bratschun, LLC
Telephone: (303) 268-0066
Facsimile: (303) 268-0065

DATE: November 18, 2005

APPLICANT: LUMPKIN


PATENT NO.: 6,957,534

FOR: REACH ADJUSTMENT MECHANISM FOR A MASTER
CYLINDER LEVER OF A HYDRAULIC DISC BRAKE

RECEIPT IS HEREBY ACKNOWLEDGED OF:

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR
APPLICANT'S MISTAKE (37 CFR §1.323) AND FOR PTO MISTAKE
(37 CFR §1.322(a)); FORM PTO/SB/44; ANNOTATED MARKED UP
DRAWINGS AND AMENDED DRAWINGS; CHECK FOR \$100

AVID:18-2/C



①

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANT: LUMPKIN

SERIAL NO.: 10/647,543

FILED: AUGUST 25, 2003

PATENT NO.: 6,957,534

ISSUED: OCTOBER 25, 2005

TITLE: REACH ADJUSTMENT MECHANISM
FOR A MASTER CYLINDER LEVER
OF A HYDRAULIC DISC BRAKE

EXAMINER: LAZO, THOMAS E.

ART UNIT: 3683

CONFIRMATION NO: 3122

Attn: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR
APPLICANT'S MISTAKE (37 CFR §1.323)
AND
FOR PTO MISTAKE (37 CFR §1.322(a))

Sir:

APPLICANT'S MISTAKE (37 CFR §1.323)

Applicant notes that several minor typographical errors, described more fully below, occurred in good faith in the above-referenced application and correction of this mistake does not involve such changes in the patent as would constitute new matter or would require reexamination. Issuance of a Certificate of Correction correcting this error is requested.

The exact page and line number where the errors occur in the specification/file history are detailed below:

In the Specification:

At page 6, line 7, delete "line 12-12 of FIG. 1" and insert --line 12-12 of FIG. 10--.

At page 6, line 8, delete "FIG. 1" and insert --FIG. 10--.

At page 6, line 27, delete "24-24" and insert --25-25--.

At page 14, line 3, delete "34" and insert --32--.

At page 14, line 16, delete "264" and insert --212--.

At page 15, line 10, delete "242" and insert --241--.

37 CFR 1.8

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to:
Attn: Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on November 18, 2005

Signature:

Name:

Elizabeth A. Salacinski

In the Figures:

In Fig. 7, delete section line label "B-B" and insert --8-8--.

In Fig. 11, replace number designations "32" with --34--.

In Fig. 11, replace number designations "34" with --32--.

In Fig. 12, replace number designations "32" with --34--.

In Fig. 12, replace number designations "34" with --32--.

An marked up copy of the drawing sheets (labeled "Annotated marked-up Drawings") showing the changes is enclosed along with a copy of the drawings as amended (labeled "Amended")

PTO MISTAKE (37 CFR §1.322(a))

In the Specification:

At page 16, line 19, delete "900-108°" and insert --90°-108°--.

In the Amendment and Remarks filed April 28, 2005:

Claim 19, line 11, delete "for moving for piston" and insert --for moving the piston--.


Attached hereto is form PTO 1050 which is suitable for printing.

Enclosed is a check in the amount of \$100.00 as required by 37 CFR §1.20(a). Please charge any deficiency or credit any excess payment to deposit account No. 19-5117.

Please send this Certificate to:

Thomas D. Bratschun
Swanson & Bratschun, L.L.C.
1745 Shea Center Drive, Suite 330
Highlands Ranch, Colorado 80129

Respectfully submitted,



James L. Brown, #48,576
Swanson & Bratschun, L.L.C.
1745 Shea Center Drive, Suite 330
Highlands Ranch, Colorado 80129
(303) 268-0066

S:\CLIENT\FOLDERS\AVID\18\18-2\CREQUEST TO CORRECT PATENT 3.DOC

Docket No: AVID.18-2/1

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

Ap 1 for use through 01/31/2004. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,957,534

DATED : October 25, 2005

INVENTOR(S) : Wayne R. Lumpkin

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 4, line 23, delete "line 12-12 of FIG. 1" and insert --line 12-12 of FIG. 10--.
At column 4, line 25, delete "FIG. 1" and insert --FIG. 10--.
At column 4, line 54, delete "24-24" and insert --25-25--.
At column 9, lines 32, delete "34" and insert --32--.
At column 9, line 52, delete "264" and insert --212--.
At column 10, line 17, delete "242" and insert --241--.
At column 11, line 8, delete "900-108°" and insert --90°-108°--.
At column 19, lines 60, delete "for moving for piston" and insert --for moving the piston--.
In Fig. 7, delete section line label "B-B" and insert --8-8--.




Fig. 7

Amended




Fig. 8

MAILING ADDRESS OF SENDER: Customer No. 25871
Swanson & Bratschun, LLC
1745 Shea Center Drive, Suite 330
Highlands Ranch, CO 80129

PATENT NO.

6,957,534

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

Docket No: AVID.18-2/

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
PTO/SB/44 (07-03)
At for use through 01/31/2004. OMB 0651-0033
U.S. Patent and Trade... Office; U.S. DEPARTMENT OF COMMERCE
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,957,534

DATED : October 25, 2005

INVENTOR(S) : Wayne R. Lumpkin

It is certified that error appears in the above-identified patent and that said Letters Patent
is hereby corrected as shown below:

In Fig. 11, replace number designations "32" with --34--.
In Fig. 11, replace number designations "34" with --32--.




Fig. 11

Amended

MAILING ADDRESS OF SENDER: Customer No. 25871
Swanson & Bratschun, LLC
1745 Shea Center Drive, Suite 330
Highlands Ranch, CO 80129

PATENT NO.

6,957,534

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

Docket No: AVID.18-2/C

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

Apj
U.S. Patent and Trademark Office

for use through 01/31/2004. OMB 0651-0033
Office; U.S. DEPARTMENT OF COMMERCE
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,957,534

DATED : October 25, 2005

INVENTOR(S) : Wayne R. Lumpkin

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Fig. 12, replace number designations "32" with --34--.

In Fig. 12, replace number designations "34" with --32--.




Fig. 12

Amended

MAILING ADDRESS OF SENDER: Customer No. 25871
Swanson & Bratschun, LLC
1745 Shea Center Drive, Suite 330
Highlands Ranch, CO 80129

PATENT NO.



6,957,534

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.






Fig. 11

Annotated Marked-up Drawing




Fig. 12

Annotated Marked-up Drawing




Fig. 7

Amended




Fig. 8




Fig. 11

Amended




Fig. 12

Amended

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.